

FOAMING ACID-N

DESCRIPTION FOAMING ACID-N is a self-foaming liquid acid cleaner containing phosphoric and nitric acid. It is very effective in removing mineral scale deposits and rust. This product may also help to provide ongoing passivation of stainless steel.

DIRECTIONS FOAMING ACID-N may be used in most food processing operations to remove protein, milkstone, water hardness and other mineral film deposits. Do not use on cement or other limestone grouting.

Manual Scrub: Use 1 to 10 oz. per gallon of water at 120°F.

Soak: Use 1 to 5 oz. per gallon of water up to 150°F.

Foam: Use 1 gallon per 40 gallons of water at temperatures not in excess of 150°F.

Always follow with a potable water rinse after use.

Consult your representative for specific applications and concentrations in your operation.

FEATURES Authorized by the USDA for use in federally inspected meat and poultry plants

SAFETY INFORMATION UTILIZE APPROPRIATE PERSONAL PROTECTIVE EQUIPMENT AS PER SDS.
HANDLE AND STORE AS INDICATED ON PRODUCT LABEL.

IF ON SKIN: In case of contact, immediately flush skin with plenty of water for at least 15 minutes while removing contaminated clothing and shoes. Get medical attention if irritation persists. Wash clothes before reusing.

IF IN EYES: In case of contact, immediately flush with plenty of water for at least 15 minutes. Get immediate medical attention.

IF SWALLOWED: Drink large quantities of water. Do not induce vomiting. Never give anything by mouth to an unconscious person. Get immediate medical attention.

IF INHALED: Immediately move to fresh air. If not breathing, give artificial respiration, preferably mouth-to-mouth. If breathing is difficult, give oxygen. Get immediate medical attention.

Consult your Safety Data Sheet for additional safety information.

FOR INDUSTRIAL USE ONLY.

DANGER!

CONTAINS PHOSPHORIC ACID.

NEVER MIX THIS PRODUCT WITH ANY PRODUCT CONTAINING
CHLORINE, AMMONIA, OR WITH ALKALINE PRODUCTS.

