

WWT AL-SU 48

Coagulant for Waste Water Treatment

DESCRIPTION WWT AL-SU 48™ is a coagulant for waste water treatment only.

DIRECTIONS Add product at 100 to 1000 ppm in order to coagulate suspended solids in waste water. For best results final water pH should be in the range of 6.0 to 8.0. Use only corrosion resistant feed pumps and tubing.

Do not reclaim treated waste water. Treated effluent should be discharged to local waste treatment facility.

SAFETY INFORMATION **UTILIZE APPROPRIATE PERSONAL PROTECTIVE EQUIPMENT AS PER SDS. HANDLE AND STORE AS INDICATED ON PRODUCT LABEL.**

IF ON SKIN: Wash off immediately with plenty of water for at least 15 minutes while removing contaminated clothing and shoes. Get medical attention if irritation persists. Wash clothes before reuse.

IF IN EYES: Rinse thoroughly with plenty of water, including under the eyelids, for at least 15 minutes. Get medical attention if irritation persists.

IF SWALLOWED: DO NOT induce vomiting. Drink large amounts of milk or water. **Call a physician or Poison Control Center immediately.** Never give anything by mouth to an unconscious person.

IF INHALED: Move to fresh air. If breathing is difficult, or irritation persists, get medical attention.

Consult your Safety Data Sheet for additional safety information.